

Division of Oil, Gas, & Mining
Mining Report

04/18/97

MINE ID: S0190039

MINE NAME: THE SANDRA J

OPERATOR: PEACOCK MINING CO, INC.

CONTACT: KERMIT BOHRER

ADDRESS: 14761 WELD CO RD 3
LONGMONT CO 80504

PHONE: (303)678-7979

Surface Owner: SITLA
Mineral Owner: SITLA

BLM #:
Lease #: ML 47374

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
	S2	NE			NW	32	19.0S	26.0E

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: ACT

Acreage: 5

Retired Date: / /

Reclaimed Date: / /

Suspended Date: / /

Minerals Mined
GOLD, SILVER, PLATINUM

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

03/18/97

/ /

04/18/97

/ /

BOND TYPE:

BOND AMOUNT:

ANNUAL REPORT YEAR:

	YTD	Total				
NONCOMP NOTICES:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
VIOLATIONS:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
REVISIONS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /
AMENDMENTS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /

COMMENTS:

GRAVEL WASH PLANT, TROMMEL 40-70 YPH. 2 HOLDING POINDS FOR TAILINGS AS WELL AS RECIRCULATING WATER. NO WATER WILL RETURN INTO THE RIVER. CONCENTRATING BOWL WITH SLUICE BOXES & CONCENTRATING TABLES. PLAN IS TO RUN BETWEEN 150-300 YDS PER DAY. WILL IMPROVE @200'X10' ROAD. COMPLETION DATE UNKNOWN. NO VARIANCES REQUESTED. DEFICIENT LETTER SENT 4/8/97. NEEDS DESCRIPTION OF ACTUAL MINING PROCESS; DRAWING OF OPERATION & DISTURBED AREA; ESTIMATE OF ACREAGE - ALSO NEED CLEARANCE FROM SITLA AND PERHAPS DWQ, WATER RIGHTS, ACOE, BLM.